

Steam Trap Survey Report

Summary Results

OK = Working
 B = Blowing (Failed Open)
 L = Leaking
 P = Plugged (Failed Closed)
 NIS = Not in Service
 RIP = Retired In Place
 NA #NAME?

#	%
154	68%
4	2%
63	28%
2	1%
2	1%
0	0%
0	0%
225	100%

Survey Date: 5/11/2015 & 5/13/2015

Facility: Madison Middle School
 Address: 4630 Madison Ave, Trumbull, CT 06611
 Company: Tunstall Corporation
 Contact: Mark Deming
 Phone:

Tag #	Quantity	Location	Application	Line PSI	Result	Manufacturer	Model	Type	Pipe Size	Orifice	Comments	Tunstall Repair Kit # or New Trap #	Net Cost Each	Repair Kit or New Trap
1	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
2	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
3	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
4	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
5	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	FT-15	FT	1"	0.218	Hot Water Heater Leaking Bad	2FP-SA-15	\$82.00	Repair Kit
6	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
7	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	FTL	FT	1 1/4"	0.312		TA-FTS-15	\$141.00	New Trap
8	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	B	Sarco	FTL	FT	1 1/4"	0.312	Return Pipe of Steam Trap is Disconnected	TA-FTS-15	\$141.00	New Trap
9	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
10	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	H	TT	3/4"	0.250		TFSA-2217	\$28.00	Repair Kit
11	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
12	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
13	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
14	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
15	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	3/4"	0.250		TFSA-2217	\$28.00	Repair Kit
16	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
17	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
18	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit

Steam Trap Survey Report

Summary Results
 OK = Working
 B = Blowing (Failed Open)
 L = Leaking
 P = Plugged (Failed Closed)
 NIS = Not in Service
 RIP = Retired in Place
 NA = NAME?

#	%
154	68%
4	2%
63	26%
2	1%
2	1%
0	0%
0	0%
225	100%

Facility: Madison Middle School
 Address: 4630 Madison Ave, Trumbull, CT 06611
 Company: Tunstall Corporation
 Contact: Mark Deming
 Phone:
 Survey Date: 5/11/2015 & 5/13/2015

Total

Tag #	Process Equipment		Line PSI	Result	Manufacturer	Model	Type	Pipe Size	Orifice	Comments	Tunstall Repair Kit # or New Trap #	Repair Kit or New Trap
	Quantity	Location										
19	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	3/4"	0.250		TFSA-2217	Repair Kit
20	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
21	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
22	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
23	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
24	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	FT-15	FT	1"	0.218	Gasket Leaking above trap	2FP-SA-15	Repair Kit
25	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
26	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
27	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	FT-15	FT	3/4"	0.218		1FP-SA-15	Repair Kit
28	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	FTL	FT	3/4"	0.218		TA-FT3-15	New Trap
29	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
30	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
31	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
32	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit
33	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	Repair Kit
34	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	Repair Kit
35	1	Crawl Space - Sprinkler Room Tunnel	9	L	Sarco	H	TT	3/4"	0.250		TFSA-2217	Repair Kit
36	1	Crawl Space - Sprinkler Room Tunnel	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	Repair Kit

Steam Trap Survey Report

Summary Results
 OK = Working
 B = Blowing (Failed Open)
 L = Leaking
 P = Plugged (Failed Closed)
 NIS = Not In Service
 RIP = Retired In Place
 NA #NAME?

#	%
154	68%
4	2%
63	28%
2	1%
2	1%
0	0%
0	0%
225	100%

Facility: Madison Middle School
 Address: 4630 Madison Ave, Trumbull, CT 06611
 Company: Tunstall Corporation
 Contact: Mark Deming
 Phone:
 Survey Date: 5/11/2015 & 5/13/2015

Total

Tag #	Quantity	Process Equipment		Line PSI	Result	Manufacturer	Model	Type	Pipe Size	Orifice	Comments	Tunstall Repair Kit # or New Trap #	Net Cost Each	Repair Kit or New Trap
		Location	Application											
37	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
38	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	FTL	FT	1 1/4"	0.312		TA-FT5-15	\$141.00	New Trap
39	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
40	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
41	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	OK	Sarco	H	TT	3/4"	0.250		TFSA-2217	\$28.00	Repair Kit
42	1	Crawl Space - Sprinkler Room Tunnel	Drip	9	L	Sarco	FT-15	FT	1"	0.218	Return Pipe of Steam Trap is Disconnected	2FP-SA-15	\$82.00	Repair Kit
43	1	Crawl Space - Back of Boilers under stairs	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
44	1	Basement Storage next to stair C	Drip	9	OK	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
45	1	Basement Storage next to stair C	Drip	9	OK	Sarco	H	TT	3/4"	0.250		TFSA-2217	\$28.00	Repair Kit
46	1	Boiler Room	MHD	9	OK	Sarco	FTL	FT	1 1/4"	0.312		TA-FT5-15	\$141.00	New Trap
47	1	Boiler Room	Drip	9	L	Sarco	FT-15	FT	1"	0.218		2FP-SA-15	\$82.00	Repair Kit
48	1	Boiler Room	Drip	9	L	Sarco	FT-15	FT	1/1/4"	0.312		3FP-SA-15	\$99.00	Repair Kit
49	1	Boiler Room	HEX	9	OK	Sarco	FTL	FT	1-1/2"	0.500		TA-FT6-15	\$283.00	New Trap
50	1	Boiler Room	HEX	9	OK	Sarco	FTL	FT	2"	0.625	Domestic Hot Water	TA-FT8-15	\$376.00	New Trap
51	1	Basement Exit	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
52	1	Basement CMC Technician	Drip	9	OK	Sarco	H	TT	1/2"	0.218		TFSA-2203	\$28.00	Repair Kit
53	1	Basement Electric Transfer	Drip	9	L	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit
54	1	Basement CMC Technician	Drip	9	OK	Sarco	H	TT	1"	0.312		TCSA-2226	\$33.00	Repair Kit